



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone	Ward No.		Ward Name				
YELAHANKA	6		Thanisandra				
Street ID	Street Name		Significant Landmark				
W0125, W0089, W0080, W0129, W0076, W0078, W0087, W	Veera Anjaneya Temple Rd, NA		R K Hegdenagara				
Segment No.	Total Length (m)						
6/S-W0125/S113728	342.65						
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	52.25	77.634890	13.071769	77.634893	13.072241	W0082	W0070
2	66.67	77.635264	13.071641	77.635267	13.071039	W0082	DEAD END
3	80.72	77.636737	13.071594	77.636698	13.070865	W0082	DEAD END
4	57.42	77.637086	13.072225	77.637065	13.071707	W0076	W0084
5	85.59	77.637087	13.073407	77.637075	13.072634	W0066	W0074

Work Details		
History of Road / Lane / Circles		
Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at R K Hegdenagara and surrounding areas in ward no 06 Byatarayanapura Sub- Division Yelahanka zone	5000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	
Tender	Work Details	Job No. / Work Code
Not a Tender	Improvement to Roads and Drains at R K Hegdenagara and surrounding areas in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-17-000006
Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/147/2016-17	09/11/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
28/02/2017	27/02/2018	Yes

Contractor Details		
Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

Zone: YELAHANKA

Ward No: 6

Ward Name: Thanisandra

Street ID: W0125,
W0089,
W0080,
W0129,
W0076, W

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-74

KRIDL

0.00

Phone No.

E-Mail ID

9449863065

Field Inspection Details

Number of Trees

Any Other Information

Name

0


DARMASINGH

Date of Inspection

Remarks

08/03/2017

COMPLETED


Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 6

Ward Name: Thanisandra

Street ID: W0125,
W0089,
W0080,
W0129,
W0076


ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಸಿ. ಬೃಹದ್ರಾಯನಪುರ ಉಪ ವಿಭಾಗ


ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ ಅಭಿಯಂತರರು
ಬೃಹದ್ರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಸಿ., ಬೆಂಗಳೂರು-74

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	08/03/2017	06/04/2017	COMPLETED
SE	VASU K M	08/03/2017	06/04/2017	COMPLETED
EE	MOHAN DAS HT	08/03/2017	06/04/2017	COMPLETED
AEE	SRIDHAR	08/03/2017	06/04/2017	COMPLETED
AE	DARMASINGH	08/03/2017	06/04/2017	COMPLETED
AE	DARMASINGH	07/03/2017	06/04/2017	COMPLETED


 ಸಹಾಯಕ ಅಧೀಕ್ಷಕರು
 ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾರಾಯನಮಠ ಉಪ ವಿಭಾಗ


 ಸಹಾಯಕ ಅಧೀಕ್ಷಕರು
 ಬ್ಯಾರಾಯನಮಠ ಉಪ ವಿಭಾಗ
 ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-74

Zone: YELAHANKA

Ward No: 6

Ward Name: Thanisandra

Street ID: W0125,
 W0089,
 W0080,
 W0129,
 W0076